



Vehicle History Summary

Plant #	856
Registration	DNC55C
Make	Isuzu
Model	D/max
VIN / Chassis #	MPATFR85JHT000890
Build Date	2017

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer Notes	Repairer
S-1543	17/12/2024	215210	0		A - Engine oil & filters		Haines Bros
S-1498	27/08/2024	203562	0		B - A + transmission	serviced as per manufacturer specifications	Picton Auto Tech
R-4086	22/08/2024			0	Battery	battery replaced 22/8/24	
O-1108	08/05/2024	0	0	0	Registration	RMS Rego Renewal exp 8/5/25	RMS
O-1089	08/05/2024	0	0	0	CTP	CTP Greenslip renewal	GIO
O-1107	08/05/2024	0	0	0	Inspection	Pink slip for rego	Picton Auto Tech
R-3941	05/04/2024			0	DPF Error	DPF valve replaced at the yard 5/4/24	Haines Bros
S-1395	21/09/2023	199275	0		A - Engine oil & filters	Engine service completed	Daniel
R-3441	04/08/2023			0	Damaged Tyre		
S-1322	10/07/2023	194121	0		A - Engine oil & filters	Engine oil and filter replaced, air and cab filter replaced, fuel filter replaced UHF fitted	Kallen
R-3445	10/07/2023			0	two way radio	Allen fitted UHF in car 10.7.23	
O-892	08/05/2023	0	0	0	Registration	Registration renewal	RMS
O-893	08/05/2023	0	0	0	CTP	Green Slip renewal	GIO
S-1064	13/02/2023	186781	0		C - Engine oil & filters	due for service change, gearbox oils, front brake pads and brake shoes on the rear and two new tyres on the front	
R-3151	13/02/2023			0	Drive Tyres	Replace and fit 2x tyres	Macarthur Tyre & Brake Service
R-3097	10/02/2023			0	Brake Pads, Brake shoes	Replaced brake shoe and brake pads before handing over car to trevor	Dan Bergmanis
R-2963	17/10/2022			0	tyre	Jake advised to take punctured tyre to South West Tyres to be repaired PO# 105476	South West Car & Truck Tyres

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer Notes	Repairer
O-727	06/05/2022	0	0	0	CTP		Tony Jordan Insurances
R-2760	06/05/2022	167150		0	Rego check	Pink slip rescheduled for Wednesday 04/05/2022 at 2pm - Failed inspection Globes to be replaced for low beam light, parker lamp and rear number plate light - Jake W replaced globes Defects booked to be cleared on Friday 06/05/2022 at 2pm - PASSED	Pro Axle - Narellan
O-726	06/05/2022	0	0	0	Registration		RMS
S-915	24/08/2021	151000	0		B - A + transmission	150,000 Km service completed as per manufactures specifications All safety checks completed as per below list No outstanding repairs Next service due at 160,000 Km	Jordan
O-569	07/05/2021	0	0	0	Registration		RMS
O-570	07/05/2021	0	0	0	CTP		Tony Jordan Insurances
S-723	23/11/2020	144148	0		A - Engine oil & filters	140,000 km service completed as per manufactures specifications All safety checks completed as per below list No outstanding repairs Next service due at 150,000 Km	Brad
R-2316	26/08/2020			0	Flat Tyre	25.8.20 Shannon Clare brought tyre back to Picton yard to be fixed/ replaced 26.8.20 Tyre taken to Picton Tyre and Mechanical and replaced PO# 102080 26.8.20 Another two tyres were replaced as per attached invoice	Picton Tyre and Mechanical
S-656	23/06/2020	127384	0		A - Engine oil & filters	130,000 Km service completed as per manufactures specifications All safety checks as per below list Replaced oil and filter Replaced fuel filter Replaced air filter No outstanding repairs Next service due at 140,000 Km	Brad
O-350	07/05/2020	0	0	0	Registration		
O-351	07/05/2020	0	0	0	CTP		

Number	Date	Kilometres	Hours	Fuel Usage	Type	Repairer Notes	Repairer
S-507	13/08/2019	90000	0		A - Engine oil & filters	90,000 Service completed as per manufacturers specification All safety checks completed as per below list Next service due at 100,000 km	Brad
R-1231	17/06/2019			0	tyre	Contacted Treadwise to replace tyre - Michael was contacted with the details to have the tyre replaced	Treadwise Tyres
R-1222	14/06/2019			0	windscreen	P & H Jennings Glass replaced windscreen on Friday 14/06/2019	P & H Jennings Heavy Machinery Glass Pty Ltd
S-480	13/06/2019	76821	0		A - Engine oil & filters	10,000 Km service completed as per manufactures specifications All safety checks as per below list No outstanding repairs Next service due at 87,000 Km	Mitch
R-1148	22/05/2019			0	bearing	Dan attending site at Lot 8 to look at car 22.5.19 - car is working fine.	Dan
O-129	06/05/2019	0	0	0	CTP		
O-128	06/05/2019	0	0	0	Registration		
S-418	11/04/2019	65935	0		A - Engine oil & filters	10,000 KM Service completed as per manufactures specifications All safety checks as per below list No outstanding repairs Next service due at 75,000 Km	Mitch
R-956	11/04/2019			0	windscreen	Replaced windscreen on Thursday 11 April 2019 at Picton workshop	P & H Jennings Heavy Machinery Glass Pty Ltd
O-4	02/05/2018	0	0	0	Registration		RMS
R-3940				0	reverse squawker		

Signed: _____

Name: _____

Date: _____